
















Columns Stirrups Schedule

<i>POS</i>	<i>SHAPE</i>	ϕ <i>(mm)</i>	<i>No.</i>	<i>L(m)</i>	<i>W(kg)</i>	<i>TOTAL W(kg)</i>
S1		10	2	8.29	5.08	10.16
S2		10	2	78.79	48.24	96.49
S3		10	1	6.03	3.69	3.69
S4		10	1	74.39	45.55	45.55
S5		10	1	7.04	4.31	4.31
S6		10	3	7.54	4.62	13.85
S7		10	3	71.63	43.86	131.57
S8		10	2	6.66	4.08	8.16
S9		10	1	63.27	38.74	38.74
S10		10	1	82.14	50.30	50.30
S11		10	1	6.53	4.00	4.00
S12		10	1	98.02	60.02	60.02
S13		10	1	8.04	4.92	4.92
S14		10	1	195.70	119.83	119.83
S15		10	1	9.38	5.75	5.75
<i>Total weight</i>						597.33

Columns Bar Size Schedule

ϕ	<i>W(kg)</i>
10	597.33